


**There must be LEAST 8 inches of clearance from the top dead center of the meter to allow access for maintenance.**

**There must be LEAST 8 inches of clearance from the top dead center of the meter to allow access for maintenance.**



**There must be LEAST 8 inches of clearance from the top dead center of the meter to allow access for maintenance.**

